QUALITY CONTROL

Name of the Work:	Construction of RCC drain and covering slab to Back side of Govt. School in Mallasandra colony, in W.No.13
Job No:	013-13-000034
Work order No:	40/13-14 D: 10-7-2013
BR No:	463/31.10.2013

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 1½ years back.

Assistant Executive Engineer
Shetty Halli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike